

Firmware Release Notes

1. Introduction

1.1 Overview

This document summarizes known bugs, workarounds, and other important issues to be aware of in this release. For further information, please contact support_voip@planet.com.tw

1.2 Copyrights

THIS DOCUMENT IS PROVIDED FOR THE PURPOSES OF PRODUCT AND PROJECT MANAGEMENT WORK IN PLANET TECHNOLOGY SOLUTIONS INC. (PLANET THEREAFTER), AIMS AT COMMUNICATING AND COORDINATING WITH CUSTOMERS, COOPERATIVE PARTNERS, AND CROSS-FUNCTIONAL PROJECT TEAMS, AND OFFERING A BETTER COOPERATION APPROACH TO ACCOMPLISH PROJECTS FOR ALL THE PARTIES MENTIONED ABOVE. MATERIALS AVAILABLE THROUGH THE WHOLE DOCUMENT MAY BE PROTECTED BY PLANET'S COPYRIGHT AND THE INTELLECTUAL PROPERTY.

1 **Firmware Information** 2 **What's New**

Model	IPX-1800N/1803/1804/2000 series
Version	1.5.0774

2.1 Feature Highlights

- Enhance system stability.

1	Fix unable to detect Ethernet PHY device issue(1244)
2	Fix timeout session could still perform action bug(1208)
3	No need to restart etx and webs since upgrade just replace the copy in flash
4	Increase dhcpd timeout value and make it run in background
5	Fix DDNS problem (1363)

2.2 Fixed Key Bugs

- ETX crash issue when POTS to virtual extension with unconditional forward to WAN SIP trunk.
- HTTP server is no response after clicking User Group list page over 100 times.
- ETX approach crash when user check CDR log on GUI if the log size is big.

3. Change Lists

3.1 GUI/SDK Changes

- In **SIP Trunk** page, a new checkbox named **DID by Privilege** is

added for configuring **DID Prefix** and **DID Stripping** to have the incoming calls directed to the trunk.

- In **SIP Trunk** page, a new checkbox named **Gateway Trunk** is added for loose checking of incoming calls.
- In **Extension of IP Phone** page, a new checkbox named **Block SIP redirection from the extension** is added for ignoring the forward settings of IP Phone and honoring the forwarding settings of IP-PBX.

3.2 Non-GUI Changes

3.2.1 Enhancement

- Enhance system stability.

3.2.2 Fixed Bugs

- Block trunk dial plan malfunction.
- ETX crash issue when POTS to virtual extension with unconditional forward to WAN SIP trunk.
- HTTP server is no response after clicking User Group list page over 100 times.
- ETX approach crash when user check CDR log on GUI if the log size is big.

Thanks for choosing PLANET products.

Best Regards ,

PLANET Tech SupportTeam

VoIP Technical Service: support_voip@planet.com.tw